AN ORDINANCE

02- -1919

BY: TRANSPORTATION COMMITTEE

AN ORDINANCE AUTHORIZING THE MAYOR OR HER DESIGNEE TO INSTALL STOP SIGNS AT THE FOLLOWING INTERSECTION: BELVEDERE DRIVE, N.W. AND McKINLEY ROAD.


NOW, THEREFORE, BE IT ORDAINED BY THE COUNCIL OF THE CITY OF ATLANTA, as follows:

SECTION 1. That STOP signs be installed at the following intersection within the City of Atlanta:

On BELVEDERE DRIVE, N.W. at McKINLEY ROAD, making McKINLEY ROAD the through street.

SECTION 2. That all ordinances and parts of ordinances in conflict herewith be and the same are hereby repealed.

Date Completed Hat a STOP sign should be installed Bilveleve Drive at McKinley Hat. Date Completed Date Completed Date Reported Action to be a STOP sign should be installed at the Bilveleve Drive at McKinley Har. Date Completed Date Reported Action as Safety hazard.	and the second s	nia, Georgia ORDINANCE	Bureau of Ti	E 0106A
Delicition Brice N. U. of Mc Kinley Ed. Organization Address 1084 McKinley Ed. U.W. Get 30518 Phone (404) 485 - 4281 CONDITION REPORTED The resident washes to have a "STOP" Sign installed at I Drie when it interests with McKinley Rd. The drivers are speeding on Beloedere Once making the love in a Safety Mayard. Did is recommended that a "STOP" Sign should be installed Beloedere Drive washing the Beloedere Drive at McKinley Rd. Beloedere Drive at McKinley Rd. There is a sentical significance. At 250ft from the interestion theorem a ventral dripog 25, a band. At 180ft them 10 a 15 foot drip There are in a cornecte accidents however to present any future collisions we have	DISTRICT# 8	Letter FAX DIS		
Organization Address Phone (404) 483 - 4281 CONDITION REPORTED The resident washes to have a "STOP" Sign installed at I Drive when it interests with McKinkay Rd. The drivers are speeding on Beloedere Drive making their lockhom a Sofely Mayerd. Date Completed October ACTION TAKEN It is recommended that a "STOP" sign should be installed Beloedere Drive at McKinkay Rd. Beloedere Drive at McKinkay Rd. The completed October and the stall start as the start and sight as the start and sight as the start and		N. V. of Mckinley Ed.	10N BeWellere Brice	LOCATION
Address Phone (404) 493 - 4281 CONDITION REPORTED The resident washes to have a "STOP" Sign installed at I Direct when it interests with McKinley Rd. The drivers are specifying on Belochere Drive making their location a Safety tragard. Date Completed October I is a secon mended that a "STOP" sign should be installed Belochere Drive at McKinley Rd. Belochere Drive at McKinley Rd. There is a ventral sight case. At 250ft from the interesting theorem a ventral dispost 25 a bend. At north them 10 a 15 foot drip. There are as corrects accordants however to present any fature collision on we have		PELKINS	TED BY MITCHELL	REPORTED BY _
The resident wishes to have a "STOP" Sign installed at I Drive when it interests with McKinley Rd. The drivers are speeding on Beloedere Drive making their location a safety tragard. Date Completed October It is recommended that a "STOP" sign should be installed Beloedere Drive at McKinley Rd. There is a ventical sight come. At 250 ft familie interesting there a ventical drip of 25 a bend. At north them is a 15 foot drop. There are no cornected accordants havever to present any future collisions were		U.W. GR 30318	ess 1084 Meknyley l	Address —
The drivers are speeding on Beloederic Drive making their location a safety hazard. ACTION TAKEN It is a commended that a "STOP" sign should be installed. Beloederic Drive at McKinley Fd. There is a ventical sight. 1 asue. At 250 ft from the intersection than is a ventical drip of 25, a bend. At 100 ft them 10 a 15 foot drop. There are no cornected accordants havever to present any future collisions, we know that the present any future collisions, we know that the second accordants havever to present any future collisions, we know that the second accordants have been accordants.	t Bolos			
Date Completed October It is a commended that a "STOP" sign should be installed Belvedere Drice at McKinley Rd. There is a ventical sight, asue. At 250 ft from the intersection there is a ventical drop of 25, a bend. At world them to a 15 foot drop. There are no cornerta accordants havever to present any future collissions, we know	at Defrence	sith Mc Kinley Rd.	is when it interests	Drive when
It is recommended that a STOP" sign should be installed Belvetere Driae at McKinley Rd. There is a ventical sight, issue. At 250 ft from the intersection theore is a ventical drop of 25, a bend. At world them is a 15 foot drop. There are no cornecte accidents however to present any future collisions, we know	100.2	Deloelere Dive merring took	when a safety hazard	location a
It is recommended that a STOP" sign should be installed Belvetere Driae at McKinley Rd. There is a ventical sight, issue. At 250 ft from the intersection theore is a ventical drop of 25, a bend. At world them is a 15 foot drop. There are no cornecte accidents however to present any future collisions, we know				
It is recommended that a STOP" sign should be installed Belvetere Driae at McKinley Rd. There is a ventical sight, issue. At 250 ft from the intersection theore is a ventical drop of 25, a bend. At world them is a 15 foot drop. There are no cornecte accidents however to present any future collisions, we know				
It is recommended that a STOP" sign should be installed Belockere Drive at McKinley Rd. There is a ventical sight, issue. It 250 ft from the intersection there is a ventical dispost 25, a bend. At world them is a 15 foot disp. There are no cornected accordants however to present any future collisions, we know				
It is recommended that a STOP" sign should be installed Belvetere Driae at McKinley Rd. There is a ventical sight, issue. At 250 ft from the intersection theore is a ventical drop of 25, a bend. At world them is a 15 foot drop. There are no cornecte accidents however to present any future collisions, we know				
Beloedere Driae at McKiuley Pd. There is a ventical sight, some. At 250 ft from the intersection there is a ventical drop of 25, a bend. At world them so a 15 foot drop. There are no cornecte accordants however to present any future collisions, we know that the second of the present any future collisions, we know that the second of the second of the present any future collisions.	sper 8th, 2002	Date Completed October		
a bend. At wort them to a 15 foot doop. There are no cornect a cordends havever to present any future collisions, we know				It is recomm
a bend. At world them is a 15 foot dost. There are no cornect a accordants havever to present any future collisions, we know	15 ft in			Déloctère Do
accidents however to present any future collisions were	ertable		, , , ,	
	Le recommend			
			U	U



15 XID ?

Saale =11=109

TRANSMITTAL FORM FOR LEGISLATION

Greg Pridgeon, Office of the Mayor

To:

To: Greg Pridgeon, Office of the Mayor	42				
From: Department of Public Works	Contact (Names): José Banda 404-330-6501				
Commissioner's Signature:	Manager's Signature: Luckerne				
Committee(s) of Purview: Nansportation	Committee Deadline: 10/28/02				
Committee Meeting Date(s): 11/13/02 & 11/27/02	City Council Meeting Date: 11/18/02				
CAPTION: AN ORDINANCE AUTHORIZING THE INSTALL STOP SIGNS AT THE BELVEDERE DRIVE, N.W. AND MO	E FOLLOWING INTERSECTION:				
BACKGROUND/PURPOSE/DISCUSSION: Received request dated October 8, 2002 to install a Stop sign at Belvedere Drive, N.W. and McKinley Road (COUNCIL DISTRICT 8).					
FINANCIAL IMPACT (if any): Cost of STOP sign and pole = \$42.					
Mayor's Staff Only					
Received by Mayor's Office: $\frac{10/29/12}{(Date)}$	Reviewed by: (Initials) (Date)				
Submitted to Council: (Date)					
Action by Committee: Approved Adversed	Held Amended				
Substitute Referred Other					